



Service Bulletin



SPECIAL COVERAGE

SUBJECT: Special Coverage Adjustment - Fuel Level Sensor Contact Wear

MODELS: 2005-2007 Buick Rainier
2005-2006 Chevrolet SSR, TrailBlazer EXT
2005-2007 Chevrolet TrailBlazer
2005 GMC Envoy XUV
2005-2006 GMC Envoy XL
2005-2007 GMC Envoy

CONDITION

On some 2005 model year GMC Envoy XUV; 2005-2006 model year Chevrolet SSR, TrailBlazer EXT, GMC Envoy XL; 2005-2007 model year Buick Rainier, Chevrolet TrailBlazer, and GMC Envoy vehicles, the contacts on the fuel level sensor may wear prematurely. This wear could cause the fuel gauge to read empty after filling the tank and cause the malfunction indicator light (MIL) to illuminate. As the fuel level in the tank drops, the MIL may turn off and the gauge may display a reading; however, the reading may indicate a slightly higher level of fuel than what is in the tank. Eventually as the contacts continue to wear, the fuel gauge will stop working and the MIL will illuminate continuously.

SPECIAL COVERAGE ADJUSTMENT

This special coverage covers the condition described above for a period of 10 years or 120,000 miles (193,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.

Dealers are to install a new design fuel level sensor. GM will pay 50% of eligible repair expenses, (parts and labor) and the customer will be responsible for the remaining 50%. The amount paid shall be calculated with reference to dealers' already approved warranty parts and labor rates.

For vehicles covered by Vehicle Service Contracts, all eligible claims with repair orders on or after August 10, 2011, are covered by at 50% by this special coverage and must be submitted using the labor operation codes provided with this bulletin. Claims with repair orders prior to August 10, 2011, must be submitted to the Service Contract provider.